

Table 1: Water Testing Results - November 9, 2018 and March 5, 2019

Building	Sampling Location	Fixture Type	11/8/2018 - testing date and Lead Results (ppb)	3/5/2019 - testing date and Lead Results (ppb)	Actions take by District for locations exceeding 15ppb
Fridley Community Center	Room 132 Sink	Faucet	34.7	1.27	
Fridley High School	Kitchen West Sink	Faucet	21	<0.5	
Fridley High School	Auditorium Concessions Sink	Faucet	82.9	13.4	
Fridley High School	Office Across from Room 113 Sink	Faucet	32.6	8.56	
Fridley Middle School	Room 121 Sink	Faucet	30.7	10.4	
Fridley Middle School	Room 115A Sink	Faucet	20.6	21.9	Taken out of Service
					Taken out of Service - this connection is below Fridley's 15ppb, but was removed from service due to attached faucet reading 25ppb
Hayes Elementary	Room 139 Fountain	Fountain	27	2.61	
Hayes Elementary	Room Across from 139 Sink	Faucet	83.9	65.7	Taken out of Service
Hayes Elementary	Room 135 Sink	Faucet	17.1	13.4	
Hayes Elementary	Room 113 Sink	Faucet	19.7	10.5	
Hayes Elementary	Room 129 Sink	Faucet	24.8	23.3	Taken out of Service
Hayes Elementary	Custodial Office Sink Left Tap	Faucet	17	14.3	
Hayes Elementary	Media Center Sink	Faucet	15.9	8.2	
Hayes Elementary	Kitchen Sink South	Faucet	20.1	9.91	
					Taken out of Service - this connection is below Fridley's 15ppb, but was removed from service due to attached faucet reading 25ppb
Hayes Elementary	Room 127 Fountain	Fountain	21.2	14.2	
Hayes Elementary	Room 127 Sink	Faucet	31.6	25	Taken out of Service
Hayes Elementary	Room 116 Sink	Faucet	15.2	135	Taken out of Service
Hayes Elementary	Room 125 Fountain	Fountain	21.3	23.1	Taken out of Service
Hayes Elementary	Room 125 Sink	Faucet	36.1	35.5	Taken out of Service
Hayes Elementary	Room 123 Sink	Faucet	51.5	16.4	Taken out of Service
Hayes Elementary	Room 114 Sink	Faucet	23.3	19.7	Taken out of Service
Hayes Elementary	Room 119 Sink	Faucet	29.9	26.7	Taken out of Service
Hayes Elementary	Room 117 Sink	Faucet	23.8	5.36	
					Taken out of Service - this connection is below Fridley's 15ppb, but was removed from service due to attached faucet reading 25ppb
Hayes Elementary	Room 110 Fountain	Fountain	21.7	8.01	
Hayes Elementary	Room 110 Sink	Faucet	38.4	21.4	Taken out of Service
Hayes Elementary	Room 115 Sink	Faucet	16	11.6	
Hayes Elementary	Room 107 Fountain	Fountain	23.1	11.9	
Hayes Elementary	Room 107 Sink	Faucet	48.3	38.3	Taken out of Service
Stevenson Elementary	Room 137 Sink	Faucet	18.2	14.3	
Stevenson Elementary	Room Across from 137 Sink	Faucet	26.9	27.4	Taken out of Service
Stevenson Elementary	Room 131 Sink	Faucet	19.6	16.1	Taken out of Service
Stevenson Elementary	Room 129 Sink	Faucet	18.5	25.1	Taken out of Service
					Taken out of Service - this connection is below Fridley's 15ppb, but was removed from service due to attached faucet reading 25ppb
Stevenson Elementary	Room 125 Fountain	Fountain	16.5	14.7	
Stevenson Elementary	Room 125 Sink	Faucet	45.5	46.7	Taken out of Service
Stevenson Elementary	Room 117 Sink	Faucet	15.2	7.62	
Stevenson Elementary	Room 115 Sink	Faucet	19.4	9.49	
Stevenson Elementary	Room 108 Sink	Faucet	24	12.5	

Note: ppb - parts per billion